

314

BG Full Synthetic ATF APPLICATION CHART

BG Full Synthetic ATF, PN 314, meets or exceeds the performance requirements of the following automatic transmission fluids.

MAKE	ATF PN
Acura	ATF-Z1
Aisin Warner	AW-1
Alfa Romeo	ALL
Allison	C-3, C-4, John Deere HD SynTran, [™] Mobil Delvac Synthetic ATF [™]
American Motors	ALL
Aston Martin	ALL
Audi	G052025A2, G052162A1, G052162A2, LT71141, G055025A2, G052990A2, G055005A2, G055005A6, G055162A2
Bentley	NONE
BMW	LA2634, LT71141, 81229400275, 83220403248, 83220403249, 83229407765, 83229407807, 83220024359, 83220026922, BMW807, TEXACO ETL-7045E, TEXACO ELT-8072B, 705/ATFD-3, 83220402413, 83220397114, 83222163514
Caterpillar	TO-2
Chrysler/Mopar	ATF 7176, +2, +3 (MS-7176E), +4 (MS-9602), AS68RC, 05189966AA, 0589977AA, 05127382AA, 68171866, 68171869AB
Citroen	973622, Z000169756
Daewoo	ALL INCLUDING LT71141
Diwa	ALL
Esso	ATF LT 71141
Fiat-Lancia	ALL
Ford	MERCON [®] (XT-2-QDR OR XT-2-QSM), MERCON [®] SP (XT-6-QSP), MERCON [®] V (XT-5-QM), MERCON [®] LV(XT-10-QLV), PREMIUM AUTOMATIC TRANSMISSION FLUID (XT-8-QAW), FNR5 AUTOMATIC TRANSMISSION FLUID (XT-9-QMM5), X-2-QDX
General Motors	DEXRON [®] , DEXRON [®] -II, -IID, -IIE, -III, -IIIG/H, DEXRON [®] -VI, GM T-IV (PN 88900925), 9986195
Honda	ATF-Z1
Hyundai	SP-II, SP-III
Idemitsu	K17, JATCO 3100 PL085, W0133-19031-54
Infiniti	ALL INCLUDING MATIC D, J, K AND S
Isuzu	ALL
Jaguar	ATF 3403 M115, 1X43 2C9010AA, JLM 20237, JLM 20238, LT71141, JATCO 3100 PL085
Jeep	SEE CHRYSLER/MOPAR
JWS	3309, 3324
Kia	SP-II, SP-III, RED 1
Land Rover	ESSO LT71141, TEXACO N402, ETL-7045E
Lexus	ALL
Man	339F, 339V1, 339V2, 339Z1, 339Z2, 339Z3
Maserati	NONE
Matra	ALL
Mazda	ATF-M III, ATF-MV, 0000-77-112E-01, 0000-77-120E-05, 0000-77-114E-01
Mercedes Benz	236.1, 236.2, 236.3, 236.5, 236.6, 236.7, 236.9, 236.10, 236.11, 236.12, 0019892103, SHELL 3403-4 115, A0019892203, 0019894503, 0019896803*

Mitsubishi	DIAMOND SP, SP-II, SP-III, SP-IV, J2, J3
Nissan	MATIC D, J, K, S
Opel	ALL
Peugeot	973622, Z000169756
Porsche	99991754700A2, 00004320509, 00004320441, SHELL 3403 M115, 99991754700, 000 043 205 28
Renault	7711218368
Rolls Royce	PL31493 PA
Saab	93160372, 93160393, 93165147
Saturn	22689186, ALL,
Shell	LA2634, ATF 3353, ATF 3403 M115
Subaru	SOA868V9241, K0140Y0700, SOA427V1500, SOA868V9240, ATF-HP
Suzuki	99980-06000, ATF 3317 SP-4B, 990B0B-01001, ALL
Texaco	ETL-7045E, ETL-8072B, N402
Toyota	TYPE T, T-II, T-III, TYPE T-IV, TOYOTA WS
Voith	55.6335.XX (G607), 55.6336.XX (G1363)
Volvo	97340, 97341, 3344208, 31256774, 31256775, 31256776, 1161521, 1161540, 1161640, 1161621
Volkswagen	G055025A2, G052162A2, G052990A2, G052025A2, G052162A1, LT71141, G055005A2, G055005A6, G055162A2
ZF Friedrichshafen AG	TE-ML: 02F, 03D, 04D, 09, 11A, 11B, 14A, 14B, 14C, 16L, 17C, SHELL LA 2634, LT 71141

BG Full Synthetic ATF is not recommended for use in the following applications:

Audi G060162A2
 BMW 83220142156, 83220142516
 Chrysler/Mopar 05127382AB
 Continuously Variable Transmissions (CVTs)
 Dual Clutch Transmissions (DCTs)
 Direct-Shift Gearbox (DSG)
 Ford Type F
 GM DEXRON®-HP
 Hyundai SPH-IV (00232-19045), 040000C90SG
 Honda DW-1
 Jaguar C2C8432
 Land Rover TYK500050, LRN 13754
 Maserati 231603
 Mercedes Benz 236.14, 236.15
 All Mercedes Benz 722.9 transmissions built after June 21, 2010 requiring ATF A0019897803
 *All Mercedes Benz 722.9 transmissions built before June 21, 2010 requiring ATF A0019896803
 Shell M-1375.4, M-1375.6, M-L12108
 Volkswagen G060162A2
 ZF-Friedrichshafen AG TE-ML: LifeGuard Fluid 6 (S671090255), LifeGuard Fluid 6 Plus (S671090281), LifeGuard Fluid 8 (AA00601304)

BG Products, Inc., accepts no liability for excessive use or misuse of this product.

Revision date 12-9-16

Revisions Under Ford and GM sections

- Removed space after Mercon®
- Added hyphen after Dexron®

5-5-16 Added to Not Recommended section

- GM Dexron HP

3-17-16 Added this PN to Chrysler/Mopar:

- 68171869AB

1-5-16 Added to Subaru:

- SOA427V1500; SOA868V9240; ATF-HP

Added to Infiniti

- Nissan Matic S ATF

7-13-15 Changed Acura:

- REMOVED “ALL” ADDED “ATF-Z1”

Removed from Jaguar:

- JDE-26444

Changed Jeep:

- REMOVED “ALL” added “SEE CHRYSLER/MOPAR”

6-25-15 Added to Allison:

- John Deere HD SynTran™
- Mobil Delvac Synthetic ATF™

5-18-15 Added this PN to Chrysler/Mopar:

- 68171866

1-18-15 Added this PN to ZF Friedrichshafen AG:

- LT 71141

11-25-14 Removed the word “ALL” from Subaru:

9-3-14 Removed these ATF PN's from Allison:

- TES-295
- TES-389

8-28-14 Added these ATF PN's to Volvo:

- 31256775
- 31256776

6-30-14 Added this ATF PN to Audi & Volkswagen:

- G055005A2, G055005A6, G055162A2

Added this to the not recommended list:

- Dual Clutch Transmissins (DCTs)

2-20-14 Added this ATF PN to Jaguar:

- JDE 26444

2-11-14 Added this ATF PN to BMW:

- 83222163514

6-19-13 Removed VW Part Number from Audi Section:

- G052182A2

6-12-13 Added this ATF PN to Subaru:

- K0140Y0700

Added this ATF PN to Idemitsu:

- W0133-19031-54

REMOVED this ATF PN from Volkswagen:

- G052182A2